



Bluff Area Affected



Bluff Area Affected

CONTEXT
PHOTO
NOS.: 1 & 2

9809 Mira Del Rio



Bluff Area Affected



Bluff Area Affected

CONTEXT
PHOTO
NO.: 3 & 4

9809 Mira Del Rio



Photo provided by property owner from across the river



Photo provided by property owner showing sluffing

CONTEXT PHOTO
PAGE NO.: 5 & 6

9809 Mira Del Rio